
















RUMBA 20




					 J14 8		 O7 2		 L9 2					
					 M3 8		 B2 4		 T9 9		 F10 6		 P14 6	
					 J12 4		 U1 4		 O1 1		 I 2		 T4 2	
					 A 28		 L 14		 S1 4		 J3 8		 G 4	

1


310/27mm  I	 T4	$\varnothing 8 \times 30 \text{ mm}$  A	$\varnothing 15/12 \text{ mm}$  C	L=20mm  D2	$\varnothing 6,3 \times 20 \text{ mm}$  M3	 F10	$\varnothing 4.0 \times 25 \text{ mm}$  P14	$\varnothing 4.0 \times 16 \text{ mm}$  P1
2	2	16	20	20	8	6	6	13
 T9	$\varnothing 20/8 \text{ mm}$  J14							
9	8							




1




2









3






4











 P7	 L2	 L
13	10	10



4.0x16mm  P1	13
---	-----------





7




†10x50mm		†3.5x13mm
		
O7	L9	P5
2	2	2

8


$\pm 6 \times 42 \text{mm}$		$L=128 \text{mm}$	$\pm 4.0 \times 30 \text{mm}$		$\pm 8 \times 30 \text{mm}$
					
B2	O1	S1	R2	L	A
4	1	2	4	4	12




x2



C




F



S1


R2

R2





B


D



RBA.608





E



L



9

H=0	$\pm 35/0 \text{mm}$	$\pm 3.5 \times 13 \text{mm}$
		
H	G	P5
4	4	8



RBA.704

x2

$\varnothing 5/16\text{mm}$  J3	 J12	L=128mm  S1	$\varnothing 4.0 \times 30\text{mm}$  R2	M4x9mm  U1	 E
8	4	2	4	4	16

