
















K30  42	T1  32	M1  36	ZP  2	PZ  4
STB  12	T2  2	W4x16  8	Z1  36	H120  5
F2  15	ODB  5	W3,5x16  10	KF50  6	Q  1






E5x13  24	ZP"9"  2
--	---


T1	W3,5x16	ODB
		
16	6	3



T1	PZ	M1	K30
			
2	2	4	4





T1	PZ	M1	K30	E5x13
				
2	2	12	12	6




ZP	ZP"9"	W4x16
		
2	2	8


12=ZP"9"
11=ZP













K30	W3,5x16	ODB
		
8	4	2
















K30	M1	T1	E5x13	RP	Q	KF50
						
12	12	12	12	6	1	6



T2	M1
	
2	8







	
H120 5	F2 15

