




MALWA M4

Mebel należy montować na miękkim podłożu	Mebel należy konserwować typowymi środkami do konserwacji mebli	Furniture should be assembled on the soft surface	Piece of furniture should be preserved by the typical furniture care substances
--	---	---	---




OKUCIE: / FITTINGS:



B1 8x35 x30	M1 12x15 x10	T1 x26	S5 3,5x16mm x1	R22 350mm x4
B3 6x30 x16	M3 10x15 x16	G2 1,4x25mm x50	T19 x1	
K5 x4	C2 x16	F36 x4	T20 x1	S7 6,3x13mm x16
L1 x1	G7 x1	K1 7,0x50 x8	S6 4 x 16 mm x8	S8 3 x 20 mm x16






1







B1 8x35 x22	M1 12x15 x10
F36 x4	R22 350mm x4
T1 x10	L1 x1
S7 6,3x13mm x16	




2






3





4






5









K5		x4
S5		3,5x16mm x1
T19		x1
T20		x1
G2		1,4x25mm x26
S6		4 x 16 mm x8

6


!!!






7



B3 6x30 x16	B1 8x35 x8	C2 x16
M3 10x15 x16	K1 7,0x50 x8	
T1 x16	G7 x1	



8



9

max.

